Name of	Langton Hall	Date of risk	22 nd August 2022	Name of who	Stuart Collett / Steve Hugh
location		assessment		undertook this risk	
				assessment	

Hazard Identified? / Risks from it?	Who is at risk?	How are the risks already controlled? What extra controls are needed?	What has changed that needs to be thought about and controlled?
Hazard - Slips, Trips & Falls Risk - Cuts, Bruises, abrasions & Sprains	Leaders, Visitors, Young Leaders, Scouts	Good housekeeping - Keeping floors clean and dry (Use signs as appropriate) Suitable adult supervision to be provided First aiders / First Aid Kit available (Main foyer and kitchen) Car park surface maintained to be as even as possible. Parking spaces for visitors with disabilities available next to hall entrance. Good lighting in car park and all rooms and corridors in hall. Users know (through hire agreement) to clear up spillages immediately and know where equipment for this is kept. Carpeted flooring at front entrances to stop rain water being carried in to building. No storage in corridors. No trailing electrical leads/cables	



Hazard - Kitchen	Leaders,	Ensure a competent adult is overseeing the young people	
Risk - Burns, Scalds, knife	Visitors,	Ensure the level of supervision and number of people in kitchen is	
cuts & Broken glass	Young	appropriate for the age of those involved	
	Leaders,	Ensuring that safety rules are discussed and understood.	
	Scouts	Limit the access to the kitchen to those only involved in the	
		activity.	
		Ensure when cooking, long hair is tied back and clothes are	
		suitable.	
		Ensure everyone understands the activity taking place and their	
		roles within the activity	
		Recognise and allow for the capabilities of the young people	
		involved	
		Hot drinks must not be left unattended near the young people.	
Hazzard - Access to loft	Leaders,	Access to be limited to adults only.	
areas	Visitors,	Ladder to be correctly installed and secured	
Risk - Fall from heigh	Young	If using stepladder check condition of ladder and have two	
	Leaders,	people working together.	
	Scouts		
Hazzard - Manual handling	Leaders,	Suitable adult supervision to be provided to ensure a safe lift.	
Risk - Back /muscle Strain /	Visitors,	Two people lift to be used where neccessary	
Strain	Young		
	Leaders,		
	Scouts		
Hazzard – Gas Equipment	Leaders,	Yearly service and safety certification – completed April 2022.	
(Boiler/Gas hobs)	Visitors,		
Risk –	Young		
Fire/Explosion/Asphyxiation	Leaders,		
	Scouts		



Hazzard – Gas Cylinders	Leaders,	Currently gas cylinders stored offsite until suitable storage facility	Suitable external storage facility required
Risk –	Visitors,	is available.	
Fire/Explosion/Asphyxiation	Young		
	Leaders,		
	Scouts		
Hazzard – Hazardous	Leaders,	Mops, brushes and strong rubber gloves provided.	
products	Visitors,	Cleaning products marked 'irritant' replaced with milder	
Risk – People cleaning, risk	Young	alternatives.	
skin problems, eg	Leaders	Cleaner trained to use products safely, eg follow instructions on	
dermatitis and eye damage,	Scouts	the label, dilute properly and never transfer to an unmarked	
from direct contact with		container.	
cleaning chemicals. Vapour		Cleaning products stored securely	
may cause breathing		Wet floor sign to be used.	
problems			
Hazzard – Electricity	Leaders,	Fixed installation correctly installed, checked by qualified	
Risk – Users risk electric	Visitors,	electrician, and inspected regularly.	
shocks or burns from faulty	Young	All repairs by qualified electrician.	
equipment or installation.	Leaders,	Portable equipment checked for visual signs of damage before	
	Scouts	use.	
		Hall users know they are responsible for any equipment used on	
		site	
		Remind users that portable equipment considered unsafe should	
		be marked and taken out of use	
Hazzard – Stored	Leaders,	Users know that they must stack tables and chairs carefully so	
Equipment	Visitors,	that they do not collapse	
Risk – Users could be	Young	Storage racking should be appropriately loaded and secured.	
injured by collapsing stacks	Leaders,		
	Scouts		



Hazzard – Fire	Fire risk assessment completed and necessary action taken	Fire evacuation plan to be placed in foyer.
Risk – If trapped, staff	Redwood Fire Ltd.	
could suffer fatal injuries	Fire equipment installed serviced and in place - ISF Fire	
from smoke	Protection – Check equipment as part of the fire alarm check,	
inhalation/burns	service yearly.	
IIIIaiation/buitis		
	Evacuation point on the opposite side on the road opposite front	
	of hall.	
	Fire evacuation plan explained to current users.	

Review due: January 2023

A risk assessment needs reviewing if circumstances change but also schedule regular reviews to ensure they are current, perhaps every 12 months? The review must include a detailed look at each element of the risk assessment in order to establish if any change is required.

